

MACH3 MU30-M3 Active Low 30 input USB Keyboard Emulator

Board and connections:



P1-P30:30 CMOS Active low switch inputs. 5V=off,0V=on (send scancode) $P31:Common\ 0V$ (Ground) for switches.

Switch circuit



Fixed KeyMappings

P1 Alt R Start P2 Alt S Stop P2 Alt X Zero X P4 Alt Y Zero Y P5 Alt Z Zero Z P6 Alt J Jog P7 Alt N Single P8 Alt W Reverse P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0 P14 Ctrl W rewind	Fixed Keylviappings		
P2 Alt X Zero X P4 Alt Y Zero Y P5 Alt Z Zero Z P6 Alt J Jog P7 Alt N Single P8 Alt W Reverse P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P1	Alt R	Start
P4 Alt Y Zero Y P5 Alt Z Zero Z P6 Alt J Jog P7 Alt N Single P8 Alt W Reverse P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P2	Alt S	Stop
P5 Alt Z Zero Z P6 Alt J Jog P7 Alt N Single P8 Alt W Reverse P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P2	Alt X	Zero X
P6 Alt J Jog P7 Alt N Single P8 Alt W Reverse P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P4	Alt Y	Zero Y
P7 Alt N Single P8 Alt W Reverse P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P5	Alt Z	Zero Z
P8 Alt W Reverse P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P6	Alt J	Jog
P9 Alt B spare P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P7	Alt N	Single
P10 Alt F spare P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P8	Alt W	Reverse
P11 Ctrl V spare P12 Ctrl Q spare P13 Ctrl O Goto 0	P9	Alt B	spare
P12 Ctrl Q spare P13 Ctrl O Goto 0	P10	Alt F	spare
P13 Ctrl O Goto 0	P11	Ctrl V	spare
	P12	Ctrl Q	spare
P14 Ctrl W rewind	P13	Ctrl O	Goto 0
	P14	Ctrl W	rewind
P15 Up arrow +Y	P15	Up arrow	+Y


P16	Down arrow	-Y
P17	Left arrow	-X
P18	Right arrow	+X
P19	Page up	+Z
P20	Page Down	-Z
P21	Space	Feed Hold
P22	Tild	RESET
P23	F5	Spindle CW
P24	F10	Feed +
P25	F11	Feed -
P26	KB Plus	Spindle +
P27	KB Minus	Spindle -
P28	Enter	Esc
P29	Esc	1
P30	Tab	2

USB Cable required:

TYPE A MALE to TYPE B MALE



Switch Example:



Software Remapping:

For MACH3 you will need to remap the Zero x,y,z using Mach3Screen Designer and ScreenTweak, (in Mach3Screen.zip) available from link below or email me if you cannot find it. https://www.machsupport.com/downloads-updates/screensets/

For more advanced remapping for the computer in general, http://www.autohotkey.com/ provides a great tool.

Warning:

Be careful not to short out connections on bottom of board to ground. Always place the board on a **non conducting** surface. Shorting the connector pins to ground may blow a fuse on the motherboard supplying +5Volts, it's a real pain to fix.

Support, questions or suggestions:

3Tronics Technical Services

3tronics@gmail.com